


Taillight with intergrated turnsignals Kawasaki VN900 Art.no.684-100

Note: removing OEM (rear) turnsignals or change to LED, requires use of replacement Highway Hawk relay 68-2525



© Motorrad Burchard GmbH advises installation by a professional mechanic. We do not accept responsibility for improper installation.

© Motorrad Burchard GmbH Lemgo – Germany