


Taillight with intergrated turnsignals

Suzuki C800 09-UP

Art.no.683-101

Note: Removing OEM (rear) turnsignals or change to LED, requires use of replacement Highway Hawk relay 683-2525



A: Turnsignal Left: Blue wire connect to OEM wire Turnsignal RightYellow wire connect to OEM wire

© Motorrad Burchard GmbH advises installation by a professional mechanic. We do not accept responsibility for improper installation.

© Motorrad Burchard GmbH Lemgo – Germany